

AMERICAN ENGINEERING GROUP



Engineering Failure Analysis - A Review

- Mr. Abraham Pannikottu
Operations Manager



ISO 9001:2000

Hubble Space Telescope

- **Background**
 - Designed in the 1970's and launched 1990
 - The first major orbiting space based observatory
- **Problem**
 - The curve to which the primary mirror was ground was incorrect, causing "spherical aberration"
 - The flaw resulted in a fuzzy focus image
- **Impact**
 - 4 costly servicing missions in 1993-2002
 - More than \$3 billion spent to date



AMERICAN ENGINEERING GROUP

TITAN IV B-27/INERTIAL UPPER STAGE-21/DSP-19

- **Background**

- Mission: Place DSP satellite into geosynchronous orbit

- **Problem**

- IUS stage 1 to IUS stage 2 interface connector failed to separate
 - Inexperienced technicians, inadequate engineering and assembly drawings led to improper application of thermal tape at connector separation plane
 - Inadequate failure modes and effects analysis on connect

- **Impact**

- Spacecraft failed to achieve proper orbit greatly reducing operational capability




AMERICAN ENGINEERING GROUP

TITAN IV B-32/CENTAUR TC-14/MILSTAR-3

• Background

- The mission was to place MILSTAR communications satellite into geosynchronous orbit
- Titan IVB core vehicle nominal
- Centaur upper stage separated from Titan vehicle



• Problem

- Flight software was not used for data validation
- Error in the manual entry of a roll rate filter
 - Correct value -1.992476
 - Value manually entered by technician -0.1992476
- Second Centaur burn failed to achieve correct orbit, resulted in low orbit

• Impact

- Greatly reduced mission capability

AMERICAN ENGINEERING GROUP

Titan IV A-20/Centaur/NRO

- **Background**


- Mission: Place NRO payload into orbit

- **Problem**

- 40 seconds after launch shorted wires caused the guidance system to reset and the vehicle to pitch and yaw beyond design loads
- Likely harness damage occurred before launch possibly due to a combination of inadequate design, faulty workmanship, rework or shipping

- **Impact**

- Resulted in structural failure and destruction of vehicle



AMERICAN ENGINEERING GROUP

GALAXY 601


- **Background**
 - August 27, 2000 spacecraft used for cable and broadcast television, national and regional radio transmission, and data relay.
- **Problem**
 - Conformal coating (prevents tin whisker growth) used to cover tin surfaces electronics was improperly applied and thus allowed tin whiskers to bridge a relay terminal causing an electrical short
- **Impact**
 - Satellite lost
 - Cost: \$500M



AMERICAN ENGINEERING GROUP

NOAA-N PRIME WEATHER SATELLITE

- **Background**
 - Television Infrared Observation Satellite (TIROS)
 - TIROS spacecraft is a polar-orbiting meteorological satellite.
- **Problem**
 - Bolts securing the satellite to a turnover cart were removed -Satellite toppled from its platform during tilting operation
 - The causes were identified as a lack of discipline, not following procedures – Responsible Test Engineer (RTE), Production Quality Control (PQC), and Production Assurance (PA) were identified as the offices of primary responsibility.
- **Impact**
 - Complete loss: \$239 Million




NASA via spaceRef.com

AMERICAN ENGINEERING GROUP

MARS POLAR LANDER MARS CLIMATE ORBITER

- **Background**
 - The failures of the Mars Climate Orbiter (MCO) and Mars Polar Lander (MPL) in 1999.
- **Problem**
 - The 'root cause' of the MCO failure was the use of data in English units that were thought to be in metric units within a segment of ground-based, navigation-related mission software.
 - The loss of MPL has been traced to premature shutdown of the descent engines, resulting from a vulnerability of the software to transient signals.
 - End-to-End testing, “...inadequate checks and balances that permitted an incomplete systems test and allowed a significant software design flaw to go undetected.”
- **Impact**
 - Loss of both missions (\$327M)



AMERICAN ENGINEERING GROUP

DELTA III 259/GALAXY-X

- **Background**

- The Mission was to deliver commercial Satellite into orbit
- Inaugural flight of Delta III

- **Problem**

- Conscious deviation from normal, proven space design analysis
- The control system tried to correct a slow natural oscillating roll that developed during the first minute of flight. The control system expended all the hydraulic fluid in the thrust vector control system
- Frequency would have been discovered if more thorough standard analysis was performed and filtered

- **Impact**

- Lost vehicle and payload
- Significant damage to product line



AMERICAN ENGINEERING GROUP

DELTA III 269/ORION-3

- **Background**

- 2nd flight of commercially developed Delta III
- The RL10B-2 engine abruptly shut down followed by tumbling of the stage

- **Problem**

- Second-stage engine stopped due to a combustion chamber breach
- Combustion chamber breach was a result of defective brazing due to poor manufacturing process controls
- Inspection results were not recognized as nonconforming because of improper translation of braze coverage design requirements to the acceptance criteria used by quality assurance procedures.

- **Impact**

- Spacecraft separation occurred placing the Orion-3 satellite in useless orbit
- No customer for the third Delta III flight
- Delta III program cancellation after third flight

AMERICAN ENGINEERING GROUP

SPACE SHUTTLE PROGRAM AUTOMATED CHECK-OUT & LAUNCH CONTROL SYSTEM

- **Background**
 - Primary objective: to reduce cost, increase performance and increase efficiency over legacy system
 - CLCS was intended to provide ground support equipment control
 - Began 1997 and canceled 2002
- **Problem**
 - Lack of disciplined software development resulted in cost growth, schedule slippage and reduced functionality
- **Impact**
 - Cost estimate increase from \$207M to \$533M
 - Cancellation of program after \$300M spent



AMERICAN ENGINEERING GROUP

EUROPEAN SPACE LAUNCHER – ARIANE 5

- **Background**

- First launch, after a decade of development costing \$7 billion.
- Designed to lift 10,000 kg into geo orbits



- **Problem**

- Launch failure caused by complete loss of guidance and attitude information 30 seconds after lift-off
- Specification and design errors in the software of the inertial reference system.
- Reuse of Ariane 4 software and values.

- **Impact**

- The destroyed rocket and its cargo were valued at \$500 million.
- Loss of future launch contracts



AMERICAN ENGINEERING GROUP

CHINESE SPACE LAUNCH FAILURE

- **Background**
 - CZ-3B was China's most powerful launch vehicle.
 - It had a payload of 5,000kg, and four liquid-fuel boosters strapped onto the core stage.
 - 1996-1998
- **Problem**
 - The CZ-3B began to veer off course two seconds after liftoff.
 - A gold-aluminum solder joint in one of the gyro servo loops failed.
 - Malfunction of the inertial guidance system
 - The vehicle and its payload hit the ground and exploded
- **Impact**
 - Crashed and devastated a village causing death and injuries
 - Cost: \$125 million dollars



AMERICAN ENGINEERING GROUP

BRAZIL SPACE PROGRAM'S SATELLITE LAUNCH VEHICLE (VLS)

- **Background**
 - Brazil attempting to develop a satellite launch vehicle
 - Four-stage rocket using solid propellants
 - Much of the technology for the VLS was derived from early Brazilian Sonda-class sounding rockets.
- **Problem**
 - Program plagued by quality problems and successive launch failures (1997-2004):
 - First Launch - Rocket off course and destroyed.
 - Second Launch -destroyed in-flight when the rocket again veered off course.
 - Third Launch - Explosion on launch pad during launch preparation
- **Impact**
 - Third Launch - 21 Lives lost
 - Processing facilities and launch pad destroyed



AMERICAN ENGINEERING GROUP

Space Shuttle

- **Background**
 - Shuttles Developed in early 1970s
 - First flight April 1981
- **Problem**
 - Challenger loss caused by a failure in the joint between the two lower segments of the right Solid Rocket Motor.
 - Columbia loss caused by a breach in the Thermal Protection System on the leading edge of the left wing.
 - Combination of design and manufacturing flaws coupled with management failures lead to both accidents.
- **Impact**
 - Destruction of Challenger and Columbia and loss of life



AMERICAN ENGINEERING GROUP

FIRESTONE TIRE RECALL

- **Background**
 - Wilderness All Terrain tires on Ford Explores manufactured at Decatur Illinois plant
 - Recalled in 2000 for tread separation
- **Problem**
 - Manufacturing equipment malfunctions
 - Lead to air void between tread and steel belt
 - Lower cohesion levels between belt and tread
 - Design defects
 - Design creates excessive stress between belt and tread
 - Inadequate testing
- **Impact**
 - Loss of life



AMERICAN ENGINEERING GROUP

SLEIPNER NORTH SEA OIL PLATFORM

- **Background**
 - Statoil (Norwegian Oil Co.), August 1991
 - Platform supported by four elongated concrete cells, one of which sank during a standard blasting operation
- **Problem**
 - Inaccurate finite element analysis performed on concrete support structure.
 - Shear stresses underestimated by 47%
 - Concrete structure failed.
- **Impact**
 - \$1B
 - Loss of platform



AMERICAN ENGINEERING GROUP

BRAZILIAN OIL COMPANY PETROBRAS OIL PLATFORM

- **Background**
 - Oil platform inaugurated in 2000
 - Located in Campos Basin, 80 miles off the coast of Rio de Janeiro
 - Supplies 5% of Brazil's total oil output
- **Problem**
 - Ignored daily bulletin advisories about valve and pump failures
 - Pressurization in platform vent system
 - Build up of Hydrocarbons
 - Rupture of tanks resulting in fire
 - Damage to flotation tower due to rupture of tanks
 - Resulting in collapse of platform
- **Impact**
 - Loss of 10 lives
 - \$500M structural loss
 - \$41.5M increase in insurance premiums



NUCLEAR WASTE REPOSITORY AT YUCCA MOUNTAIN


- **Background**
 - First long-term geologic repository for spent nuclear fuel and high-level radioactive waste.
 - NRC requires nuclear facilities to develop a quality assurance program
- **Problem**
 - DOE auditors identified significant problems with data sources, validation of scientific models, and software development.
 - Data sets could not be traced back to their original sources
 - No standardized process to develop scientific models needed to simulate geological events
 - No process for ensuring that software being developed to support the models would work
- **Impact**
 - Continuing delay of repository licensing, operation and stockpiling of spent fuel



Thank you

- Product Development**
- **Failure Analysis**
 - **Finite Element Analysis**
 - **Prototyping**

(ISO 9001 : 2000)



“Progress through continuous innovation, technology and customer success”